


Repair Request #7948

ID	#7948
Kind	Repair
Campus	WPB South
Requester	Ednix Amado
Description	El sink donde de afuera donde se lava el mop esta roto y cuando se abre el agua esta gotenado por debajo , es de plastico , no estoy segura si debe swr reparadp o debe ser cambiaido. gracias
Priority	Urgent
Due	2026-09-18
Target Date	
Remarks	[2026-09-16 20:22:12] Assignment updated by arturo: Duvan
IP	73.138.133.111
Reviewed	Yes
Reviewed By	
Reviewed At	
Authorized By	arturo
Authorized At	2026-09-16 20:19:39
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	
Started	2026-09-18 19:46:30
Status	Completed
Assigned To	Duvan
Submitted At	2026-09-16 10:15:38

Updated At	2026-09-18 19:46:30
Archived At	

Original Photos

Original Photo 1



Original Photo 3



Completion Photos

Completion Photo 1

