

Repair Request #6222

ID	#6222
Kind	Maintenance
Campus	WPB South
Requester	Maintenance
Description	replacement of damaged wooden ceiling panels
Priority	No Rush
Due	2026-06-17
Target Date	
Remarks	[2026-09-05 21:21:07] Assignment updated by arturo: Duvan
IP	216.77.93.48
Reviewed	Yes
Reviewed By	
Reviewed At	
Authorized By	arturo
Authorized At	2026-09-05 21:19:42
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	
Started	2026-09-10 16:48:30
Status	Completed
Assigned To	Duvan
Submitted At	2026-06-17 20:26:30
Updated At	2026-09-18 20:39:46

Archived At	
-------------	--

Original Photos

Original Photo 1



Original Photo 2



Completion Photos

Completion Photo 1

