

Repair Request #7680

ID	#7680
Kind	Repair
Campus	WPB
Requester	Aliya
Description	The deck is leaking water from the roof
Priority	Urgent
Due	
Target Date	
Remarks	[2026-09-05 20:58:45] Assignment updated by arturo: Duvan [2026-09-05 20:58:45] Admin update by arturo: Duvan, hay que subir al techo y revisar que los gutters no estén obstuidos. Limpiar ramas y hojas de los gutters
IP	107.219.75.93
Reviewed	Yes
Reviewed By	arturo
Reviewed At	2026-09-05 20:54:07
Authorized By	arturo
Authorized At	2026-09-05 20:55:44
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	
Started	2026-09-10 18:45:32
Status	Completed
Assigned To	Duvan
Submitted At	2026-08-31 09:37:51

Updated At	2026-09-10 18:45:32
Archived At	

Original Photos

Original Photo 1



Original Photo 2



Completion Photos

Completion Photo 1

