

Repair Request #7834

ID	#7834
Kind	Repair
Campus	Delray
Requester	Mr. Arturo
Description	Duvan: El plomero del Landlor instalo nuevo drenaje afuera del efficiency hay que asegurarse que el pasto articlficial quedo correctamente re instalado
Priority	Extremely Urgent
Due	
Target Date	
Remarks	[2026-09-06 13:24:50] Assignment updated by arturo: Duvan
IP	162.204.191.17
Reviewed	Yes
Reviewed By	arturo
Reviewed At	2026-09-06 12:14:45
Authorized By	arturo
Authorized At	2026-09-06 12:14:55
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	
Started	2026-09-12 08:36:00
Status	Completed
Assigned To	Duvan
Submitted At	2026-09-06 12:14:36
Updated At	2026-09-12 08:36:00

Archived At	
-------------	--

Original Photos

Original Photo 1



Completion Photos

Completion Photo 1

