

Repair Request #6222

ID	#6222
Kind	Maintenance
Campus	WPB South
Requester	Maintenance
Description	replacement of damaged wooden ceiling panels
Priority	No Rush
Due	2026-06-17
Target Date	
Remarks	
IP	216.77.93.48
Reviewed	Yes
Started	
Status	Reviewed
Assigned To	
Submitted At	2026-06-17 20:26:30
Updated At	2026-06-17 20:42:06
Archived At	

Original Photos

Original Photo 1



Original Photo 2



Completion Photos

No completion photos attached.