

Repair Request #7322

ID	#7322
Kind	Repair
Campus	Boca
Requester	Ms Carolina
Description	Las puertas de entrada a los salones deben cerrar completamente y automáticamente (con el brazo cierrapuertas de arriba). La única que está cerrando correctamente es la del salón #4.
Priority	Urgent
Due	
Target Date	
Remarks	Buenas tardes, Estoy haciendo seguimiento a las puertas que aun no cierran. La inspeccion se vence en sept 03. Gracias La puerta del salón #5 necesita el brazo que permite que el sistema de cierre funcione correctamente. [2026-09-16 20:27:16] Assignment updated by arturo: Miltito
IP	73.179.9.92
Reviewed	Yes
Reviewed By	
Reviewed At	
Authorized By	Legacy V3.2.9 migration
Authorized At	2026-09-01 14:37:50
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	

Started	2026-08-19 09:02:53
Status	Completed
Assigned To	Miltito
Submitted At	2026-08-14 16:46:44
Updated At	2026-09-16 20:27:16
Archived At	

Original Photos

No original photos attached.

Completion Photos

Completion Photo 1

