

Repair Request #6227

ID	#6227
Kind	Maintenance
Campus	WPB South
Requester	Maintenance
Description	install floodlights that were removed because they weren't working
Priority	No Rush
Due	
Target Date	
Remarks	
IP	216.77.93.48
Reviewed	Yes
Started	
Status	Reviewed
Assigned To	
Submitted At	2026-06-17 20:30:55
Updated At	2026-06-17 20:43:06
Archived At	

Original Photos

Original Photo 1



Original Photo 2



Completion Photos

No completion photos attached.