

Repair Request #6706

ID	#6706
Kind	Repair
Campus	Fort
Requester	Emily Guerrero
Description	Both bathrooms in the teachers' lounge are experiencing flushing issues. The toilets are not flushing properly and require multiple attempts to clear. This issue is affecting both restrooms in the teachers' break room. It appears that the water tanks are not filling up as expected.
Priority	Urgent
Due	2026-07-28
Target Date	
Remarks	
IP	76.108.236.103
Reviewed	No
Started	
Status	Submitted
Assigned To	
Submitted At	2026-07-27 14:05:57
Updated At	
Archived At	

Original Photos


Original Photo 1



Original Photo 2



Original Photo 3



Completion Photos

No completion photos attached.