


Repair Request #6808

ID	#6808
Kind	Maintenance
Campus	Fort
Requester	Emily Guerrero
Description	Also should be resolved with the gutters install. The Nido II classroom also appears to have flooded over the weekend. There is water on the classroom floor, but we are unable to determine where it came from. The bathroom next to the classroom is dry, and the sinks and cabinets are also dry, so there is no obvious source of the water. The only other possibility we can think of is that it may have come from the classroom next door.
Priority	Urgent
Due	2026-08-03
Target Date	
Remarks	
IP	76.108.236.103
Reviewed	Yes
Reviewed By	
Reviewed At	
Authorized By	
Authorized At	
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	
Started	2026-08-03 10:20:59
Status	Archived

Assigned To	Milton
Submitted At	2026-08-03 08:13:39
Updated At	2026-08-10 11:47:41
Archived At	2026-08-12 15:45:47

Original Photos

Original Photo 1



Completion Photos

Completion Photo 1

