# Repair Request #8008

| | |
|---|---|
| **ID** | #8008 |
| **Kind** | Repair |
| **Campus** | Fort |
| **Requester** | Emily Guerrero |
| **Description** | The hinge on the bathroom door located between Casa I and Casa II has completely detached from both the door and the wall/frame. As a result, the door is not functioning properly and requires repair as soon as possible. Please inspect and repair the hinge to ensure the door is secure and safe for daily use. Thank you. |
| **Priority** | Keep it on the list |
| **Due** | 2026-09-28 |
| **Target Date** | |
| **Remarks** | Our inspection is coming up soon, so we would greatly appreciate having this repair completed as soon as possible. Thank you! |
| **IP** | 76.108.236.103 |
| **Reviewed** | Yes |
| **Reviewed By** | System — Direct to Authorization |
| **Reviewed At** | 2026-09-21 09:47:56 |
| **Authorized By** | |
| **Authorized At** | |
| **Denied By** | |
| **Denied At** | |
| **Denial Reason** | |
| **Reopened By** | |
| **Reopened At** | |
| **Reopen Note** | |
| **Started** | |
| **Status** | Awaiting Authorization |
| **Assigned To** | |

| | |
|---|---|
| **Submitted At** | 2026-09-21 09:47:56 |
| **Updated At** | |
| **Archived At** | |

## Original Photos

### Original Photo 1

### Original Photo 2

### Original Photo 3

## Completion Photos

No completion photos attached.