Repair Request #8282

ID	#8282
Kind	Maintenance
Campus	WPB
Requester	Dora
Description	A ver que tan factible es cubrir esa reja con malla verde- es el pasillo que va del playground al edificio de abajo
Priority	No Rush
Due	2026-11-30
Target Date	
Remarks	[2026-10-11 15:03:35] AUTHORIZED and ASSIGNED to Duvan by arturo: Duvan: Favor de darle Pressure Cleaning a esa area.
IP	76.109.1.55
Reviewed	Yes
Reviewed By	System — Direct to Authorization
Reviewed At	2026-10-11 13:57:02
Authorized By	arturo
Authorized At	2026-10-11 15:03:35
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	
Started	
Status	Authorized
Assigned To	Duvan
Submitted At	2026-10-11 13:57:02

Updated At	2026-10-11 15:03:35
Archived At	

Original Photos

Original Photo 1



Additional Photos / Progress

No additional photos attached.

Completion Photos

No completion photos attached.