

Repair Request #6206


ID	#6206
Kind	Repair
Campus	Pompano
Requester	Cintia Layton
Description	Main door button release is coming off the wall.
Priority	Urgent
Due	2026-06-19
Target Date	
Remarks	Thank you!
IP	76.109.1.55
Reviewed	No
Started	
Status	Submitted
Assigned To	
Submitted At	2026-06-17 14:36:16
Updated At	
Archived At	

Original Photos

Original Photo 1



Original Photo 2



Original Photo 3



Completion Photos

No completion photos attached.