

Repair Request #6438

ID	#6438
Kind	Maintenance
Campus	Delray
Requester	Fabiola Ruggiero
Description	ajustar la tubería debajo de los 3 lavaplatos de la cocina, está floja y se cae cuando abren el agua y se inunda a veces.
Priority	Urgent
Due	2026-07-10
Target Date	
Remarks	
IP	73.139.108.227
Reviewed	Yes
Started	2026-07-12 11:16:22
Status	Completed
Assigned To	Duvan
Submitted At	2026-07-06 14:08:36
Updated At	2026-07-12 11:16:22
Archived At	

Original Photos

Original Photo 1



Original Photo 2



Completion Photos

Completion Photo 1

