

Repair Request #8169

ID	#8169
Kind	Repair
Campus	WPB South
Requester	Ednix Amado
Description	Durante horas de la tarde la pintura de esta pared en la calae de nido donde esta el aire acondicionado central , se empezo a llenar de agua , no estamos seguros si hay alguna filtracion o si fue por la lluvia, gracias
Priority	Urgent
Due	2026-10-04
Target Date	
Remarks	[2026-10-02 13:09:30] AUTHORIZED and ASSIGNED to Duvan by arturo: Duvan, revisa el sellado de la ventana por fuera y sellar para que no entre el agua por la ventana. Probablemente se acumulo por las fuertes lluvias de los dias pasados
IP	73.138.133.111
Reviewed	Yes
Reviewed By	System — Direct to Authorization
Reviewed At	2026-10-01 16:48:04
Authorized By	arturo
Authorized At	2026-10-02 13:09:30
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	
Started	2026-10-22 08:33:51
Status	In progress
Assigned To	Duvan


Submitted At	2026-10-01 16:48:04
Updated At	2026-10-22 08:33:51
Archived At	

Original Photos

Original Photo 1



Original Photo 2



Original Photo 3



Completion Photos

No completion photos attached.