


Repair Request #8393

ID	#8393
Kind	Repair
Campus	Pompano
Requester	Sonya Rezvanjou
Description	The metal chain is disconnected from the black, circular water stopper that opens and closes when you flush the toilet in room 4. We are having to pour water in the toilet to be able to flush it manually.
Priority	Urgent
Due	
Target Date	
Remarks	[2026-10-20 11:01:56] AUTHORIZED and ASSIGNED to Miltito by arturo: Ms. Sonya can you provide a photo of this request? Thanks
IP	76.109.1.55
Reviewed	Yes
Reviewed By	System — Direct to Authorization
Reviewed At	2026-10-20 09:18:57
Authorized By	arturo
Authorized At	2026-10-20 11:01:56
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	
Started	2026-10-21 21:21:11
Status	Completed
Assigned To	Miltito
Submitted At	2026-10-20 09:18:57

Updated At	2026-10-21 21:21:11
Archived At	

Original Photos

Original Photo 1



Completion Photos

No completion photos attached.