Repair Request #8630

ID	#8630
Kind	Repair
Campus	Pompano
Requester	Sonya Rezvanjou
Description	The bathroom toilet in classroom 5 is cracked.
Priority	No Rush
Due	
Target Date	
Remarks	[2026-11-22 17:13:59] AUTHORIZED and ASSIGNED to Miltito by arturo: Miltito - Revisa este Toilet a ver si se puede cambiar el tanque o hay que cambiar el toilet completo.
IP	76.109.1.55
Reviewed	Yes
Reviewed By	System — Direct to Authorization
Reviewed At	2026-11-17 14:43:12
Authorized By	arturo
Authorized At	2026-11-22 17:13:59
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	
Started	
Status	Authorized
Assigned To	Miltito
Submitted At	2026-11-17 14:43:12

Updated At	2026-11-22 17:13:59
Archived At	

Original Photos

Original Photo 1



Original Photo 2



Original Photo 3



Additional Photos / Progress

No additional photos attached.

Completion Photos

No completion photos attached.