

Repair Request #6596

ID	#6596
Kind	Maintenance
Campus	Delray
Requester	Fabiola Ruggiero
Description	El Aire Acondicionado de Nido está caliente. Marca 77 grados F
Priority	Extremely Urgent
Due	2026-07-20
Target Date	
Remarks	
IP	73.139.108.227
Reviewed	Yes
Started	2026-07-26 07:35:15
Status	Completed
Assigned To	
Submitted At	2026-07-20 10:55:01
Updated At	2026-07-26 07:35:15
Archived At	

Original Photos

Original Photo 1



Completion Photos

No completion photos attached.