

Repair Request #7446

ID	#7446
Kind	Maintenance
Campus	WPB
Requester	Aliya
Description	Front office window panes and Door casing needs to be painted
Priority	Keep it on the list
Due	2026-08-27
Target Date	
Remarks	
IP	107.219.75.93
Reviewed	Yes
Reviewed By	
Reviewed At	
Authorized By	
Authorized At	
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	
Started	2026-08-22 17:42:35
Status	Archived
Assigned To	
Submitted At	2026-08-19 10:14:26
Updated At	2026-08-22 17:42:35

Archived At	2026-08-24 15:49:55
-------------	---------------------

Original Photos

Original Photo 1



Original Photo 2



Original Photo 3



Completion Photos

Completion Photo 1



Completion Photo 2

