

Repair Request #8008

ID	#8008
Kind	Repair
Campus	Fort
Requester	Emily Guerrero
Description	The hinge on the bathroom door located between Casa I and Casa II has completely detached from both the door and the wall/frame. As a result, the door is not functioning properly and requires repair as soon as possible. Please inspect and repair the hinge to ensure the door is secure and safe for daily use. Thank you.
Priority	Keep it on the list
Due	2026-09-28
Target Date	
Remarks	Our inspection is coming up soon, so we would greatly appreciate having this repair completed as soon as possible. Thank you!
IP	76.108.236.103
Reviewed	Yes
Reviewed By	System — Direct to Authorization
Reviewed At	2026-09-21 09:47:56
Authorized By	
Authorized At	
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	
Started	
Status	Awaiting Authorization
Assigned To	

Submitted At	2026-09-21 09:47:56
Updated At	
Archived At	

Original Photos

Original Photo 1



Original Photo 2



Original Photo 3



Completion Photos

No completion photos attached.