

Repair Request #6427

ID	#6427
Kind	Repair
Campus	Pompano
Requester	Cintia Layton
Description	cleaning main school address sign.
Priority	Urgent
Due	2026-07-06
Target Date	
Remarks	
IP	76.109.1.55
Reviewed	Yes
Started	2026-07-06 17:16:24
Status	In progress
Assigned To	BEC Signage Company will be repairing this
Submitted At	2026-07-02 16:30:07
Updated At	2026-07-06 17:16:24
Archived At	

Original Photos

Original Photo 1



Completion Photos

No completion photos attached.