


Repair Request #7282

ID	#7282
Kind	Repair
Campus	Fort
Requester	Emily Guerrero
Description	Milton: Ve las fotos de esta orden. Hay que volver a amarrar la lona con cintitas. La parte que está rota, a ver como podemos repararla...
Priority	Keep it on the list
Due	2026-08-14
Target Date	
Remarks	The tarp covering the playground fence needs to be repaired or replaced. There are multiple areas where the tarp is damaged and torn, and some sections are no longer properly attached to the fence. We kindly ask that this repair be completed as soon as possible. The tarp is needed to keep the playground fence properly covered for the safety and privacy of our students. Completion Update (2026-08-12 20:29:51): cheque y le puse a todo
IP	76.108.236.103
Reviewed	Yes
Reviewed By	
Reviewed At	
Authorized By	
Authorized At	
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	


Started	2026-08-12 19:34:47
Status	Archived
Assigned To	Milton
Submitted At	2026-08-12 14:59:59
Updated At	2026-08-12 20:29:51
Archived At	2026-08-13 12:39:19

Original Photos


Original Photo 1



Original Photo 2



Original Photo 3



Completion Photos

No completion photos attached.