


Repair Request #7836

ID	#7836
Kind	Repair
Campus	Mr.Arturo
Requester	Mr.Arturo
Description	Duvan instalar lampara para reemplazar el foco exterior y colocar una caja de exterior con dos contactos para ponerle un smart contact de lis que tengo
Priority	No Rush
Due	
Target Date	
Remarks	[2026-09-06 13:25:19] Assignment updated by arturo: Duvan
IP	73.179.9.92
Reviewed	Yes
Reviewed By	arturo
Reviewed At	2026-09-06 13:24:56
Authorized By	arturo
Authorized At	2026-09-06 13:25:04
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	
Started	2026-09-15 19:53:13
Status	Completed
Assigned To	Duvan
Submitted At	2026-09-06 13:22:56
Updated At	2026-09-15 19:53:13

Archived At

Original Photos

Original Photo 1



Original Photo 2



Completion Photos

Completion Photo 1

