


Repair Request #6340


ID	#6340
Kind	Maintenance
Campus	Pompano
Requester	Cintia Layton
Description	painting inside and out playground door in room 4
Priority	Urgent
Due	2026-06-26
Target Date	
Remarks	
IP	76.109.1.55
Reviewed	No
Started	
Status	Submitted
Assigned To	
Submitted At	2026-06-19 13:38:57
Updated At	
Archived At	

Original Photos

Original Photo 1



Original Photo 2



Completion Photos

No completion photos attached.