

Repair Request #6818

ID	#6818
Kind	Repair
Campus	Delray
Requester	Damaris Silaghi
Description	The pipe under the sink is leaking.The sink is located in Casa classroom,the one next to the playground door.
Priority	Extremely Urgent
Due	2026-08-04
Target Date	
Remarks	
IP	73.139.108.227
Reviewed	Yes
Reviewed By	
Reviewed At	
Authorized By	
Authorized At	
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	
Started	2026-08-03 21:03:55
Status	Archived
Assigned To	
Submitted At	2026-08-03 15:23:18
Updated At	2026-08-03 21:03:55

Archived At	2026-08-10 11:10:17
-------------	---------------------

Original Photos

Original Photo 1



Original Photo 2



Original Photo 3



Completion Photos

Completion Photo 1

