

Repair Request #6206

ID	#6206
Kind	Repair
Campus	Pompano
Requester	Cintia Layton
Description	Main door button release is coming off the wall.
Priority	Urgent
Due	2026-06-19
Target Date	
Remarks	Thank you!
IP	76.109.1.55
Reviewed	Yes
Reviewed By	
Reviewed At	
Authorized By	
Authorized At	
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	
Started	2026-07-29 15:23:52
Status	Archived
Assigned To	Milton
Submitted At	2026-06-17 14:36:16
Updated At	2026-07-29 15:23:52

Archived At


2026-07-31 12:57:04

Original Photos

Original Photo 1



Original Photo 2



Original Photo 3



Completion Photos

No completion photos attached.