

Repair Request #6225

ID	#6225
Kind	Maintenance
Campus	WPB South
Requester	Maintenance
Description	Plastering and painting a wall in poor condition.
Priority	No Rush
Due	
Target Date	
Remarks	
IP	216.77.93.48
Reviewed	Yes
Reviewed By	
Reviewed At	
Authorized By	
Authorized At	
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	
Started	2026-07-19 12:30:54
Status	Archived
Assigned To	
Submitted At	2026-06-17 20:28:24
Updated At	2026-07-29 21:17:51

Archived At	2026-08-24 15:51:06
-------------	---------------------


Original Photos

Original Photo 1



Completion Photos

Completion Photo 1



Completion Photo 2

