

Repair Request #6441


ID	#6441
Kind	Repair
Campus	Delray
Requester	Fabiola Ruggiero
Description	el Dispensador de Jabón de Nido, se encuentra aislado de la pared y esta caído, estamos esperando inspeccion y debe ser reparado urgente, gracias
Priority	Extremely Urgent
Due	2026-07-10
Target Date	
Remarks	
IP	73.139.108.227
Reviewed	Yes
Started	2026-07-07 20:41:03
Status	Completed
Assigned To	Duvan
Submitted At	2026-07-06 14:13:35
Updated At	2026-07-07 20:41:03
Archived At	

Original Photos

Original Photo 1



Original Photo 2



Original Photo 3



Completion Photos

Completion Photo 1

