


Repair Request #6568

ID	#6568
Kind	Maintenance
Campus	Delray
Requester	Fabiola Ruggiero
Description	la puerta que va hacia el playground, por el pasillo lateral tiene un clavo afuera. se ve peligroso. es la salida que utiliza Primis para ir al Playgroud n
Priority	Urgent
Due	2026-07-20
Target Date	
Remarks	Fixed!
IP	73.139.108.227
Reviewed	Yes
Started	2026-07-17 18:32:05
Status	Archived
Assigned To	Duvan
Submitted At	2026-07-17 14:05:08
Updated At	2026-07-22 13:34:16
Archived At	2026-07-22 13:34:22

Original Photos

Original Photo 1



Original Photo 2



Completion Photos

Completion Photo 1

