


Repair Request #6683

ID	#6683
Kind	Maintenance
Campus	Pompano
Requester	Sonya
Description	Tech will be schedule an inspection of the unit. HVAC Not working in break room
Priority	Urgent
Due	
Target Date	
Remarks	Priority is moved to no rush, and Room AC has been setup to operate during regular hours until unit is repaired.
IP	76.109.1.55
Reviewed	Yes
Started	
Status	Reviewed
Assigned To	HVAC Team
Submitted At	2026-07-23 13:03:30
Updated At	2026-07-23 13:24:58
Archived At	

Original Photos

Original Photo 1



Original Photo 2



Completion Photos

No completion photos attached.