

Repair Request #7318

ID	#7318
Kind	Repair
Campus	WPB South
Requester	Ednix Amado
Description	El tubo del sink del bano de las maestras se volvio a romper , y cuando los ninos se lavan las manos en el sink de la clase se vota el agua por el sink del bano, es imporyante repararlo pronto muchas gracias
Priority	Extremely Urgent
Due	2026-08-14
Target Date	
Remarks	
IP	73.138.133.111
Reviewed	Yes
Reviewed By	
Reviewed At	
Authorized By	
Authorized At	
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	
Started	2026-08-18 20:03:18
Status	Archived
Assigned To	
Submitted At	2026-08-14 10:39:52

Updated At	2026-08-18 20:03:18
Archived At	2026-08-24 15:52:59

Original Photos


Original Photo 1



Original Photo 2



Original Photo 3



Completion Photos

Completion Photo 1

