

Repair Request #7408

ID	#7408
Kind	Repair
Campus	Fort
Requester	Emily Guerrero
Description	The shelf has come apart and appears to be in need of repair. It looks like the pieces may be able to be put back together, possibly with glue or another appropriate method. If possible, please repair the shelf and secure it so it can be safely used again. Thank you!
Priority	Keep it on the list
Due	2026-08-21
Target Date	
Remarks	
IP	76.108.236.103
Reviewed	Yes
Reviewed By	
Reviewed At	
Authorized By	
Authorized At	
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	
Started	2026-08-27 08:00:06
Status	Archived
Assigned To	
Submitted At	2026-08-18 10:28:47

Updated At	2026-08-27 08:00:06
Archived At	2026-08-27 21:11:18

Original Photos

Original Photo 1



Original Photo 2



Completion Photos

Completion Photo 1

