

Repair Request #7770

ID	#7770
Kind	Repair
Campus	Ms.Dora
Requester	Mr. Arturo
Description	DEstapar el excusado de la casa de Ms. Dora, llevar la máquina. Es el baño del departamentito nuevo. U R G E N T E
Priority	Extremely Urgent
Due	2026-09-03
Target Date	
Remarks	[2026-09-03 20:13:22] Assigned by arturo: Miltito
IP	76.109.1.55
Reviewed	Yes
Reviewed By	arturo
Reviewed At	2026-09-03 19:55:28
Authorized By	arturo
Authorized At	2026-09-03 20:13:06
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	
Started	2026-09-03 20:14:04
Status	Archived
Assigned To	Miltito
Submitted At	2026-09-03 16:49:17
Updated At	2026-09-03 21:55:49

Archived At	2026-09-16 22:46:32
-------------	---------------------

Original Photos

No original photos attached.

Completion Photos

No completion photos attached.