

Repair Request #7903


ID	#7903
Kind	Repair
Campus	Boca
Requester	Ms. Carolina
Description	La barra del suelo del salon# 2 esta desprendida. La deje junto al dispensador de agua. las fotos estan adjuntas.
Priority	Urgent
Due	
Target Date	
Remarks	
IP	73.179.9.92
Reviewed	Yes
Reviewed By	arturo
Reviewed At	2026-09-14 17:09:57
Authorized By	arturo
Authorized At	2026-09-14 17:13:22
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	
Started	2026-09-14 17:13:49
Status	Archived
Assigned To	Milton
Submitted At	2026-09-11 08:39:55
Updated At	2026-09-14 17:13:49

Archived At


2026-09-14 17:13:54

Original Photos

Original Photo 1



Original Photo 2



Original Photo 3



Completion Photos

No completion photos attached.