


Repair Request #6406

ID	#6406
Kind	Repair
Campus	WPB
Requester	Aliya
Description	The Kitchen sink , needs to be fixed
Priority	Keep it on the list
Due	2026-07-17
Target Date	
Remarks	this looks Damaged and clipping option makes it look bad
IP	107.219.75.93
Reviewed	Yes
Started	2026-07-11 11:56:55
Status	Completed
Assigned To	
Submitted At	2026-07-01 09:24:59
Updated At	2026-07-11 11:56:55
Archived At	

Original Photos

Original Photo 1



Completion Photos

Completion Photo 1

