Repair Request #8211

ID	#8211
Kind	Repair
Campus	Pompano
Requester	Sonya Rezvanjou
Description	Lid of classroom 1 toilet in the first bathroom cracked when something above it fell. Item was moved to prevent another crack.
Priority	No Rush
Due	
Target Date	
Remarks	[2026-10-07 18:05:48] AUTHORIZED and ASSIGNED to Miltito by arturo: Ve si se puede conseguir una tapa igual en Home Depot.
IP	76.109.1.55
Reviewed	Yes
Reviewed By	System — Direct to Authorization
Reviewed At	2026-10-06 16:32:11
Authorized By	arturo
Authorized At	2026-10-07 18:05:48
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	
Started	
Status	Authorized
Assigned To	Miltito
Submitted At	2026-10-06 16:32:11

Updated At	2026-10-07 18:05:48
Archived At	

Original Photos

Original Photo 1



Original Photo 2



Additional Photos / Progress

No additional photos attached.

Completion Photos

No completion photos attached.