

Repair Request #6346

ID	#6346
Kind	Maintenance
Campus	Pompano
Requester	Cintia Layton
Description	Paint water stain and clean vent. Very dusty. In room 5
Priority	Extremely Urgent
Due	2026-06-19
Target Date	
Remarks	
IP	76.109.1.55
Reviewed	No
Started	
Status	Submitted
Assigned To	
Submitted At	2026-06-19 13:49:58
Updated At	
Archived At	

Original Photos

Original Photo 1



Original Photo 2



Completion Photos

No completion photos attached.