


Repair Request #6349

ID	#6349
Kind	Maintenance
Campus	Pompano
Requester	Cintia Layton
Description	Painting interior door and exterior
Priority	Urgent
Due	2026-06-26
Target Date	
Remarks	
IP	76.109.1.55
Reviewed	No
Started	
Status	Submitted
Assigned To	
Submitted At	2026-06-19 14:17:50
Updated At	
Archived At	

Original Photos

Original Photo 1



Original Photo 2



Original Photo 3



Completion Photos

No completion photos attached.