Repair Request #7519

ID	#7519
Kind	Maintenance
Campus	WPB South
Requester	Ednix Amado
Description	Por favor limpiar la maleza de alrededor del pasillo de la entrada , de los neumaticos de colores en el paryqr de atras , y al rededor de las raices del palygtound grande, gracias
Priority	No Rush
Due	2026-08-31
Target Date	
Remarks	
IP	73.138.133.111
Reviewed	Yes
Reviewed By	
Reviewed At	
Authorized By	Legacy V3.2.9 migration
Authorized At	2026-08-26 19:56:16
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	
Started	2026-08-26 19:56:16
Status	Completed
Assigned To	
Submitted At	2026-08-24 13:36:20

Updated At	2026-08-26 19:56:16
Archived At	

Original Photos

Original Photo 1

Original Photo 2

Original Photo 3

Completion Photos

Completion Photo 1