

Repair Request #6225

ID	#6225
Kind	Maintenance
Campus	WPB South
Requester	Maintenance
Description	Plastering and painting a wall in poor condition.
Priority	No Rush
Due	
Target Date	
Remarks	
IP	216.77.93.48
Reviewed	Yes
Started	2026-07-19 12:30:54
Status	In progress
Assigned To	
Submitted At	2026-06-17 20:28:24
Updated At	2026-07-19 12:30:54
Archived At	

Original Photos

Original Photo 1



Completion Photos

No completion photos attached.