


Repair Request #7907

ID	#7907
Kind	Repair
Campus	Pompano
Requester	Sonya Rezvanjou
Description	The weather strip peeled off of the front entrance door. It needs to be replaced.
Priority	No Rush
Due	
Target Date	
Remarks	[2026-09-14 17:15:03] Assignment updated by arturo: Miltito
IP	76.109.1.55
Reviewed	Yes
Reviewed By	arturo
Reviewed At	2026-09-14 17:06:20
Authorized By	arturo
Authorized At	2026-09-14 17:06:30
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	
Started	2026-09-15 20:31:43
Status	Completed
Assigned To	Miltito
Submitted At	2026-09-11 15:59:56
Updated At	2026-09-15 20:31:43

Archived At	
-------------	--

Original Photos

Original Photo 1



Original Photo 2



Completion Photos

Completion Photo 1

