Repair Request #8471

ID	#8471
Kind	Maintenance
Campus	WPB
Requester	Aliya
Description	Diaper storage cabinet has to be changed - new one is kept in the hallway
Priority	Urgent
Due	2026-10-29
Target Date	
Remarks	[2026-10-27 16:16:57] AUTHORIZED and ASSIGNED to Miltito by arturo: Miltito: Hay que remover el gabinete que esta en la primera foto y en su lugar instalar el que esta en la entrada en el mismo lugar donde esta actualmente el mueble de pañales. Cualquier duda, me puedes preguntar.
IP	107.219.75.93
Reviewed	Yes
Reviewed By	System — Direct to Authorization
Reviewed At	2026-10-27 12:56:37
Authorized By	arturo
Authorized At	2026-10-27 16:16:57
Denied By	
Denied At	
Denial Reason	
Reopened By	
Reopened At	
Reopen Note	
Started	
Status	Authorized
Assigned To	Miltito
Submitted At	2026-10-27 12:56:37

Updated At	2026-10-27 16:16:57
Archived At	

Original Photos

Original Photo 1



> **Photo Note:** Remove this one

Original Photo 2



> **Photo Note:** Put this on the same place

Additional Photos / Progress

No additional photos attached.

Completion Photos

No completion photos attached.